


[Click Here](#)



Thank you for the answer. Accelerometer does not show up under "Add and remove Programs", so I deleted accelerometer.exe, That seems to work But there is another problem: The AMD videocard, which should be part of the system, does not work. I installed the respective driver downloaded from HP-site. The installation seemingly worked with no error message, but in device manager no second videocard shows up.What can I do to get the second videocard working? Systeminformation below.I apologize for the inconvenience.Many thanks in advance.pututSystemmodell HP ProBook 6570bSystemtyp x64-basierter PCSystem-SKU A5E64AVProzessor Intel(R) Core(TM) i5-3320M CPU @ 2.60GHz, 2601 MHz, 2 Kern(e), 4 logische(r) Prozessor(en)BIOS-Version/-Datum Hewlett-Packard 68ICE Ver. F.68, 13.07.2017SMBIOS-Version 2.7Version des eingebetteten Controlllers 66.56BIOS-Modus UEFI I have an HP Probook 6570b..The brightness settings aren't working, if I do Fn+F9/F10 then it should increase the brightness but this one isn't.If I recall correctly there is a "hotkey driver". But going to HP.com and letting it detect my laptop and list drivers, can't see it at the moment.I have Win10I notice that for Win7 it has hotkey driver listed. But having installed it, it's not working.Note- I can use win10 mobility controls brightness adjustm,ent there. And maybe autohotkey could solve it but anyhow. In Win7 there was a "hotkey driver" but it doesn't work on win10. Hello dear readers,i am the proud owner of an HP 6570b. This Model has an dedicated graphic card, Radeon HD 7570m i think. But i cannot turn it on and use it.i reinstalled Windows 10 and now it is only possible to use the internal Intel HD4000.If i use the detection utility from Radeon it does not find the graphic card. It only shows me the Intel one.If i install the driver from the HP Website an error occurs while installation. The error says the install manager cannot be installed.If i install the driver from the AMD Website the same error occurs.When i look in the Windows device Manager there are two devices wich are not recogncied by the system1.) Code 28Is there something i have to install also? Why is WIndows not finding the driver by itself as usual? Would it be an solution using windows 8?greetingsChris Microsoft Windows 10 (64-bit) my laptop just today got this weird display problem where the task bar is not at the bottom. there is this gray bar at the bottom and the task bar appears above that. also arount quater way from the top there seems to be a dead zone. a horizontal invisible line that does not display anything. even the cursor gets lost there. anyone know what the problem might be or better yet the solution. The HP ProBook 6570b is very stable and features excellent build quality.The battery has a capacity of 55 Wh.The 90 watt AC adapter is suitably potent.The display bezel and the display prevent annoying reflections thanks to being matte surfaces.WLAN and volume can be easily adjusted with the illuminated quick access buttons.Having disabled the touchpad with a double-tap, the integrated LED illuminates.The Fn special function keys are marked with white lettering.

Hp probook 6570b drivers. Hp probook 6570b displayport driver.