

Click to prove
you're human



[illegible]

SunDash Palm Beach Tan 32 Super Power Tanning Bed Manual SunDash R-40SS Tanning Bed Manual SunDash Radius 252 Tanning Bed Manual SunDash Radius SR-48 Tanning Bed Manual SunDash Spa 16 Tanning Bed Manual SunDash Spa 24 Tanning Bed Manual SunDash XXS 35 Seashell Tanning Bed Manual SunDash XXS-35 Tanning Bed Manual SUNLITE & SUNFIRE Sunfire 36 Pro Booth Tanning Bed Manual Sunfire Platinum Pro 48X Tanning Bed Manual SUNSCAPE Sunscape 756V Tanning Bed Manual SUNSOURCE Sunsource 3000XP Tanning Bed Manual Sunsource 6000 VSS Tanning Bed Manual Sunsource 10000 Elite Tanning Bed Manual TAN AMERICA Tan America Matrix L33 Tanning Bed Manual Tan America Matrix Solarix X2 Tanning Bed Manual ULTRASUN Ultrasun E6 TSU Edition Tanning Bed Manual Ultrasun I8 TSU Edition Tanning Bed Manual Ultrasun Q6/0 TSU Edition Tanning Bed Manual Ultrasun Q6/2 TSU Edition Tanning Bed Manual Ultrasun Q10 TSU Edition Tanning Bed Manual Ultrasun Q14 TSU Edition Tanning Bed Manual Ultrasun Q18 TSU Edition Tanning Bed Manual UWE UWE Cayenne XTT Tanning Bed Manual UWE Silver Bullet SE Tanning Bed Manual UWE Tropical Series 32 GB, 41 U.P.P Tanning Bed Manual UWE IBED EVG Tanning Bed Manual UWE IDOME Swing 8 Min Tanning Bed Manual UWE Lotus Tanning Bed Manual Skip to content In the tanning salon, you can easily raise the tanning bed canopy thanks to the support of the tanning bed shocks. When you sit down, the canopy is lowered smoothly and rests gently above it. After the sunbathing, the canopy can be raised again without any effort. This is all thanks to the shock absorbers hidden underneath that smoothly and safely raise or close the bathing bed.GASTAC, a leading Chinese tanning bed shocks manufacturer, offers advanced production technology and a skilled manufacturing team. For custom stainless steel gas springs, contact sales@gastac.com. For standard tanning bed gas strut specifications, visit the GASTAC online store for easy purchasing and reliable solutions.GASTAC Tanning Bed Shocks provide reliable canopy support, ensuring smooth and safe operation. They are designed as replacement shocks, compatible with major tanning bed brands like Wolff and Sunquest. These shocks maintain consistent lifting and lowering, enhancing user comfort. GASTAC focuses on durability, offering a long-lasting solution for tanning bed maintenance.Below are the brands or models of Tanning Bed Shocks that GASTAC can replace:-Check your existing tanning bed shocks: You can check to see if there are any numbers printed on the side of your current gas struts.-Find the label on the back of the bed: Every tanning bed has a label on the back that will show the brand, model and year of the tanning bed.-If you don't see the model you need, we have a variety of gas struts available, so please contact us directly.Tanning bed shocks, also known as gas springs or hydraulic shocks, are components used to support the opening and closing of the canopy (the top part) of a tanning bed. They provide the necessary force to help lift and lower the canopy smoothly and safely, preventing sudden slamming or difficulty in handling.Assisted Lifting: Tanning bed struts reduce effort to lift the heavy canopy. Controlled Closing: They slow the canopy's descent to prevent slamming. Safety: Tanning bed gas springs stop the canopy from closing too quickly, reducing injury risk. Replacement: Replace worn tanning bed struts to keep the bed operating smoothly and safely.To choose the right size tanning bed shocks, measure the length of the old shocks when extended. Check weight requirements for the canopy, as shocks are rated by force (in pounds). Match mounting hardware type and orientation, and select gas springs that match original specifications for smooth operation.Tanning bed shocks, or gas springs, typically need replacement when they can no longer hold the tanning bed canopy open or when it starts to sag or close unexpectedly. Here are some key indicators for when to replace tanning bed shocks:Reduced Lifting Power: If the canopy struggles to stay open or needs extra force, the shocks are likely weakening. Wear Signs: Rust, oil leaks, or damage mean it's time to replace them. Noisy Movement: Squeaks or grinding sounds suggest worn parts. Typical Lifespan: Shocks last 3-5 years but may vary with use and humidity.Gas springs are integral components in many devices, including tanning beds, where they help manage the smooth opening and closing of the bed's canopy. However, once gas springs lose pressure or start showing signs of wear, they cannot be repaired and must be replaced. This is because the internal gas chamber, which provides the necessary force, can no longer function effectively once compromised.PRECAUTIONS: In the context of tanning beds, which often rely on two tanning bed gas springs for balanced operation, it's essential to replace both springs simultaneously, even if only one has failed. Replacing just one can lead to uneven support, causing additional strain on the new spring and the bed's structure. Over time, this imbalance can result in further issues, such as misalignment, increased wear, and potentially even safety hazards. By replacing both gas springs at the same time, you ensure that the tanning bed operates smoothly and maintains its structural integrity, providing a safe and consistent user experience.We offer one of the most extensive selections of gas springs, shocks, and lifts in the industry. Our inventory includes shocks, struts, and springs compatible with a wide range of tanning bed brands, such as American Quality MFG, ACN Solart, Alisun, Atlantis, Soltron, Dr. Muller, Electric Sun, ESB, Forever Tan, Garda Sun, HEX, Hollywood Tan, ITS, JK Ergoline, JK Soltron, Kettler, Klafsun, Klaus, Sunliner, Mega Max, Montego Bay, Pro Sun, Royal Sun, SCA, Shaw, Silver Solarium, Solana, Solaris, Sonnenbraune, Sontegra, Sportaredo, Star Power, Sun Dash, Sun Dazzler, Sun Industries, Sun Quest, Sun Star, Sun Vision, Sunal, Tan America, Tanses, Wolff, Ultra Bronze, UWE, Velocity, Vita Sun, and many more.